

DELIVERING RESULTS.



Decommissioning

project highlights

- Prepped three bridge-connected facilities and a satellite facility for abandonment
- Supported well services plug and abandonment campaign
- Set up temporary living quarters
- Removed two gas train coolers and an 80-ton pancake deck
- Flushed and abandoned mercury contaminated 24-inch pipeline
- Removed gas pipeline from topside structure
- Installed and removed Seatrax crane
- Completed all final prep work for abandonment and heavy lift removal

UN
O
C
C
E
S
S



project highlights

Decommissioning

Plug and abandonment campaign support

Location: Gulf of Mexico

Year: 2012

Duration: 3 years

Peak manpower: 15

Subcontractors: 1

Services provided:

Project Management

Construction

Scaffolding

Fabrication

Project achievements

Zero recordable safety incidents



Whatever your asset management needs, Danos has the resources, expertise and experience to serve as your strategic partner. With our comprehensive service offering and proven safety performance we can help you get the job done right.